

---

**From:** Jason E Williams (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JASO508559]  
**Sent:** 1/11/2016 9:24:43 PM  
**To:** Cathy C Taylor (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Cathy25]  
**Subject:** Re: Questions

My mistake...the toe drain has end of pipe limits.

Sent from my iPhone

> On Jan 11, 2016, at 8:31 PM, Cathy C Taylor (Services - 6) <cathy.c.taylor@dom.com> wrote:

>  
> Thank you

>  
> Sent from my iPhone

>  
>> On Jan 11, 2016, at 8:29 PM, Jason E Williams (Services - 6) <Jason.E.Williams@dom.com> wrote:

>>  
>> Cathy,  
>> I'm looking into this right now. I'm trying to remember the toe drain limits I've got to look at the permit but I'm away from my computer for another 30 45 minutes or so. These limits are for tidal waters so if I remember correctly that changes how the limits are calculated versus a mixing zone. The only outfalls that were issued end of pipe limits are the ones that discharge into the beaver pond. I also sent an email to GAI to confirm which lab they used I don't have the raw data for possum.

>> Jason

>>  
>> Sent from my iPhone

>>  
>>> On Jan 11, 2016, at 7:57 PM, Cathy C Taylor (Services - 6) <cathy.c.taylor@dom.com> wrote:

>>>  
>>> What lab did the analysis for the toe drain samples? Also are the limits in the table based on a mixing zone or end of pipe compliance?

>>>  
>>> Sent from my iPhone